MIDMARK • RITTER

Control PC Boards to fit Old & New Style
Midmark® •Ritter® UltraClave® M9 & M11 sterilizers!

**NEW**

RPI Part #MIB132
OEM Part #002-1992-00

CONTROL PC BOARD (REFURBISHED)
• Includes: Mounting Bracket
• Please Note: When shipping RPI your non-operational PC Board, **you must** include the Mounting Bracket in order to receive full credit!
Fits: Chassis
Models: M9 -020 & -022 Serial # V1697650 thru Present; and M11 -020 & -022 Serial # V1697650 thru Present

Fits New Style M9 & M11

**RPI Part #MIB129**
OEM Part #022-0762-00

CONTROL PC BOARD (REFURBISHED)
• Includes: Mounting Bracket
• Please Note: When shipping RPI your non-operational PC Board, **you must** include the Mounting Bracket in order to receive full credit!
Fits: Chassis
Models: M9 -020 & -022 Serial # prefixes RN, RR & Serial # V2200 thru V1697649; and M11 -020 & -022 Serial # prefixes RS, RV & Serial # V2200 thru V1697649

Fits New Style M9 & M11

Fits Old Style M9

**RPI Part #MIB130**
OEM Part #002-0434-00/
002-0434-03

CONTROL PC BOARD (REFURBISHED)
• Mounting Bracket not included
• Please Note: This PC Board **Does Not** include the Mounting Bracket. When shipping your non-operation PC Board to RPI, do not include your Mounting Bracket. You will need your Mounting Bracket to install the refurbished PC Board!
Fits: Chassis
Models: M9 -001 thru -019 with Serial # prefixes CZ, DA, DB, DX, DY, FD & OM

Fits Old Style M11

RPI Part #MIB131
OEM Part #002-0501-00

CONTROL PC BOARD (REFURBISHED)
• Mounting Bracket not included
• Please Note: This PC Board **Does Not** include the Mounting Bracket. When shipping your non-operation PC Board to RPI, do not include your Mounting Bracket. You will need your Mounting Bracket to install the refurbished PC Board!
Fits: Chassis
Models: M11 -001 thru -019 with Serial # prefixes ES, ET, FP, FR & GB

About RPI's Control PC Board Exchange Program

Here's How the $100 Credit Exchange Program Works.
1) Place an order for a Control PC Board (PCB), and RPI will send a shipping box and prepaid UPS return label to you. You will not pay for shipping when using this box.
2) Using the shipping box and UPS return label, ship as follows:
   • **Include** the PCB and Mounting Bracket if shipping the *New Style* M9/M11 PCB (OEM Part #002-1992-00/022-0762-00). If you do not Include the Mounting Bracket, you will only receive a $75 Credit instead of $100.
   • **Do not include** the Mounting Bracket if shipping the *Old Style* M9/M11 PCB (OEM Part #'s 002-0434-00/002-0434-03/002-0501-00).
3) Once the non-operational board has been received by RPI and verified that it is in reasonable condition without burn holes, a replacement PCB will be shipped to you. Your invoice will reflect the cost of the board plus the $100 credit for the Core.

Important Information. PC Board performance verified and tested and Quality Control test printout is included with each PC Board. 90 Day Warranty.

Warning. To avoid damaging the replacement PC Board and possibly voiding the warranty, check the condition of the *Heater and/or Pulse Solenoid* prior to installing the replacement PC Board. DO NOT use PC Board in 220V or version "D" sterilizers.

SECTION
10

PAGE
1025

UPDATED
05/22

rpi® replacement parts industries, inc. *A Healthcare Components Group Company*

You asked for It ... RPI Now Offers the Red Colored PC Board to fit newer Midmark•Ritter UltraClave M9 & M11 sterilizers with a Green LCD Display!

RPI now offers the **red colored PC Boards** that fit the newer Midmark sterilizers with a green display through our PC Board Exchange Program - receive a $100* credit with the bracket, and $75.00* without the bracket. These boards fit the M9 -020 thru -022 Serial # V1697650 thru Present and the M11 -020 thru -022 Serial # V1697650 thru Present. Just ask for the Control PC Board (RPI Part #MIB132).

Don't forget, we already have a program for the **green colored PC Boards** that also fit newer Midmark sterilizers with a green display. This PCB fits the M9 -020 thru -022 with serial number prefixes RN, RR, and Serial # V2200 thru V1697649; and the M11 -020 thru -022 with serial number prefixes RS, RV, and Serial # V2200 thru V1697649. Just ask for RPI Part #MIB129. Also note that both the red and green boards will only be exchanged for the exact same style board - red for red, and green for green - this is the only way in which we can keep this program working.

* Credit is given after RPI has inspected the PC Board and found it to be in good condition.

RPI Part #MIB132

**PC Boards to fit Midmark® • Ritter® UltraClave® M9 & M11 Sterilizers!**

RPI now offers four Control PC Boards to fit Midmark® • Ritter® UltraClave® M9 & M11 Sterilizers!

RPI Part #MIB132
Fits new style
M9 & M11

RPI Part #MIB129
Fits new style
M9 & M11

RPI Part #MIB130
Fits old style
M9

RPI Part #MIB131
Fits old style
M11