




## New Parts to fit Midmark • Ritter Tables and Chairs

**WARNING:** When attaching hydraulic hoses to the cylinders, torque the hose fittings between 55 - 60 Inch Pounds only. Additional torque could damage the threads in the cylinder.


**RPI Part #MIH104**  
OEM Part #002-0004-00

**POWER HOSE**  
Fits: Connects Motor/Pump to bottom of Hydraulic Cylinders  
Models: 110




**RPI Part #MIH106**  
OEM Part #002-0005-00

**RETURN HOSE**  
Fits: Connects Motor/Pump to top of Hydraulic Cylinders  
Models: 110




**RPI Part #MIH105**  
OEM Part #002-0109-00

**POWER HOSE**  
Fits: Connects Motor/Pump to bottom of Hydraulic Cylinders  
Models: 105\*




**RPI Part #MIH109**  
OEM Part #002-0110-00

**RETURN HOSE**  
Fits: Connects Motor/Pump to top of Hydraulic Cylinders  
Models: 105\*




**RPI Part #MIH108**  
OEM Part #002-0099-00

**POWER HOSE**  
Fits: Connects Motor/Pump to bottom of Hydraulic Cylinders  
Models: 105\* & 305



**RPI Part #MIH107**  
OEM Part #002-0098-00

**RETURN HOSE**  
Fits: Connects Motor/Pump to top of Hydraulic Cylinders  
Models: 105\* & 305




**RPI Part #MIH100**  
New OEM Part #002-0144-00  
Old OEM Part #002-0054-00

**POWER HOSE**  
Fits: Pump to Base  
Models: 106 & 306




**RPI Part #MIH101**  
New OEM Part #002-0143-00  
Old OEM Part #002-0053-00

**RETURN HOSE**  
Fits: Pump to Base  
Models: 106 & 306




**RPI Part #MIH103**  
OEM Part #002-0096-00

**POWER HOSE**  
Fits: Pump to Base  
Models: 107 & 307



**RPI Part #MIH102**  
OEM Part #002-0095-00

**RETURN HOSE**  
Fits: Pump to Base  
Models: 107 & 307



\* See Chart on Back for Models and Serial Number Breakdowns

**For your convenience – Cable Ties also available!**

**RPI Part #RPT085**

**CABLE TIE (8" BLACK)**  
• 25 per package



**RPI Part #RPT279**

**CABLE TIE (8" BLACK)**  
• 25 per package




**RPI Part #RPT375**

**CABLE TIE (12" BLACK)**  
• 25 per package



**RPI Part #MIC089**  
OEM Part #002-0094-00


**BASE CYLINDER**  
Fits: Table Base  
Models: 105, 107, 305 & 307



Includes Cable Ties

**RPI Part #MIC111**  
OEM Part #002-0100-00


**BACK CYLINDER**  
Fits: Table Back  
Models: 105 & 305



Includes Cable Ties

**RPI Part #MIC112**  
OEM Part #002-0137-00


**TILT CYLINDER**  
Fits: Table Base  
Models: 112, 113 & 117\*



Includes Cable Ties

**RPI Part #MIC113**  
OEM Part #002-0271-00


**TILT CYLINDER**  
Fits: Table Base  
Models: 117\* & 317



Includes Cable Ties

**RPI Part #MIC114**  
OEM Part #002-0346-00

**BACK CYLINDER**  
Fits: Table Back  
Models: 117\*, 119\*, 311, 317, 318 & 319\*



Includes Cable Ties

**rpi replacement parts industries, inc.**

CALL (800) 221-9723 • FAX (818) 882-7028 • EMAIL [order@riparts.com](mailto:order@riparts.com) • WEBSITE [www.riparts.com](http://www.riparts.com)

The above parts are manufactured by Replacement Parts Industries, Inc. to fit Midmark•Ritter equipment. All product names used in this document are trademarks or registered trademarks of their respective holders. WEB 07/09

RPI PART #	OEM PART #	DESCRIPTION	MODELS with Prefix and Serial # Breakdown <i>Note: Part fits all prefixes and all serial #'s for models listed if not otherwise noted.</i>
MIC089	002-0094-00	BASE CYLINDER	105-001 thru -006; 107; 305-001 thru -004; 307-001 thru -007
MIC111	002-0100-00	BACK CYLINDER	105-001 thru -006; 305-001 thru -004
MIC112	002-0137-00	TILT CYLINDER	112-001; 113-001; 117-001 thru -003 serial #'s AJ1000 thru AJ3143
MIC113	002-0271-00	TILT CYLINDER	117-001 thru -003 serial #'s AJ3144 & FE1000 thru present; 317-001
MIC114	002-0346-00	BACK CYLINDER	117-001 thru -003 serial #'s FE1000 thru present; 119-001 thru -016 serial #'s BY2006, CA1191, DF2695, EM1000, EN1000, EY1000, EZ1000 & HK1000 thru present; 311-005; 317-001; 318-001; 319-003 thru -006 with prefixes HN, KK, KL & V
MIH100	002-0144-00 002-0054-00	POWER HOSE	106-001 thru -004; 306-001 thru -003
MIH101	002-0143-00 002-0053-00	RETURN HOSE	106-001 thru -004; 306-001 thru -003
MIH102	002-0095-00	RETURN HOSE	107; 307-001 thru -007
MIH103	002-0096-00	POWER HOSE	107; 307-001 thru -007
MIH104	002-0004-00	POWER HOSE	110-001
MIH105	002-0109-00	POWER HOSE	105-001 thru -002 serial #'s G1000 thru G1324 and H1000 thru H1019
MIH106	002-0005-00	RETURN HOSE	110-001
MIH107	002-0098-00	RETURN HOSE	105-001 thru -006 serial #'s G1325, H1020, V1000, CF1000, CG1000 & CA1000 thru present; 305-001 thru -004
MIH108	002-0099-00	POWER HOSE	105-001 thru -006 serial #'s G1325, H1020, V1000, CF1000, CG1000 & CA1000 thru present; 305-001 thru -004
MIH109	002-0110-00	RETURN HOSE	105-001 thru -002 serial #'s G1000 thru G1324 and H1000 thru H1019



# replacement parts industries, inc.

P.O. Box 5019 • Chatsworth, California • 91313-5019

PRESORTED STANDARD  
U.S. POSTAGE PAID  
VAN NUYS, CA  
PERMIT #2399

• Address Service Requested •

— An ISO 9001 Certified Company —



**RPI Presents New Parts to fit Midmark® Ritter® Tables and Chairs!**

For more parts to fit  
Midmark® Ritter® Tables and Chairs  
including • More Cylinder Kits  
• More Return & Power Hose Kits  
• Relays • Switches • Hydraulic Fluid  
— Go to [www.rpiparts.com](http://www.rpiparts.com)

